

August 01, 2024

Changelog

F-Link 2.9.0

IMPROVED

- New texts in all languages for the JA-116E and JA-156E – requires a firmware update of the control panel and keypad
-

FIXED

- Erroneous bus current measurement display in specific cases
- Change of JA-152A communication loss setting in EN50131-1, level 2 profile
- Fix common segment feature in segment keyboard simulator
- Removing the settings of the assigned PG for JA-156J
- The JA-190X's internal settings allowed AT commands to be sent incorrectly
- Minor internal fixes and code optimizations

JA-102K | JA-152K | JA-103K | JA-107K

FIXED

- Change of GSM operator switching algorithm for SDC
- Fixed accidental restart of the control panel caused by specific cases of controlling PG outputs via SMS commands
- Minor internal fixes and code optimizations

JA-156E | JA-116E

NEW

- The firmware for the JA-116E and JA-156E touch keypads, which introduces the new function "Section and PG status preview screen", allows you to arm sections and control PGs without authorization according to the internal keypad settings. This feature also requires the latest version of the control panel firmware.
-

FIXED

- Occasional random jams and infinite loading indicated by the logo
- Occasional random keyboard restart
- Fixing the behaviour when arming with obstacles without authorization
- Displaying PGs after authorization to which the user is not authorized
- Non-functional wake-up by touch in certain cases
- Non-functional switching of thermometer pages when using 8 or more thermometers
- Prevent leaving the service mode when a tamper is active in sections that are not assigned in the keyboard
- Minor internal fixes and code optimizations

JB-160N-PLUG | JB-161N-PLUG | JB-162N-PLUG | JB-163N-PLUG

FIXED

- Minor internal fixes and code optimizations